
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/22/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition.	
Manhole_ID: S03AA1003MH	Test ID: <u>D1032-026012</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S01AA1013MH
0			Dye Test Visible	@ IG, 0.5gpm
4			Dye Test Visible	@ IG, 5gpm
12.30000019			Dye Test Visible	@ IR, 1 gpm
15.60000038			Dye Test Visible	@ IR, 1gpm
20.70000076			Dye Test Visible	@ IR, 0.5gpm
23.79999924			Dye Test Visible	@ IR, 0.25gpm
25.70000076			Dye Test Visible	@ IR, 0.1gpm
36			Dye Test Visible	@ IR, 0.1gpm
50			Abandoned Survey	DYE FLOOD COMPLETED

City of Baltimore Wet Smoke and Dyed	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/22/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp □ Wet □	Supervisor: JAW
Manhole_ID: S03AA1003MH	Test ID: <u>D1032-026012</u>	Notification Made: NA (Residents, Fire, 311)